



Activity: Any activity taking place in the church	Date of first risk assessment: 7 th January 2024
Location: All Saints Church	Time/frequency:
Name of leader with responsibility: Rev Beverly Watson	Date to be reviewed: 7 th January 2024

What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
	and Surrounds and Repairs notebook hanging in the foyer of the c	hurch for the reporting of any faults, wear and tear, or anything the	at needs fixing.			_
Dangerous Surfaces	Uneven surface of car park	• Car park surface currently in excellent condition and will be maintained to be as even as possible. Users to report any problems with the car park surface to the churchwardens.				
	Slips, trips and falls caused by wet surfaces	• Flood lighting will come on automatically in the car park when you walk near the front entrance to the church, to report in Faults booklet if it is not working.				
		• Users to clear up spillages immediately and safely remove debris. Use correct mops from the cupboard in the disabled toilet, or paper towels from dispenser on the wall under the bell tower. Use 'wet				





Location: All Saints	y taking place in the church Church h responsibility: Rev Beverly Wat	Date of first risk assessn Time/frequency: Son Date to be reviewed: 7 th	-	24		
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
	Slips, trips and falls caused by physical damage and corresponding debris	 floor' sign if appropriate. Mats at entrances to stay in place to stop rain water being carried in. ANY accidents to be reported to the church via the accident reporting book stored by the First Aid Box in the Church Foyer. 				
Vehicle movement	Pedestrians could suffer serious injury if struck by cars entering/leaving car park or moving in it.	 For large events, parking to be controlled by Marshalls wearing hi-viz vests. Car park well lit – if not working report in Faults and Repairs book hanging from the noticeboard in the church foyer. Users (especially those with children) to be aware of cars in the car park 				
Electrical equipment	Electric shocks or burns from faulty equipment or installation	 Safety plugs to be kept in sockets. Portable equipment owned by the church will be checked following HSE advice. Will show PAT label 				





Location: All Sain Name of leader w	vith responsibility: Rev Beverly Wat	Time/frequency: Son Date to be reviewed: 7 ^t	^h January 2024			
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
		Users are responsible for any of their own equipment used on site.				
		Users must check portable electrical equipment for visual signs of damage before use and any unsafe equipment should be noted in Faults and Repairs book.				
		All unsafe equipment to be removed from the church				
Fire	If trapped, risk of fatal injuries from smoke inhalation/burns – elderly, children and others with restricted mobility may be at special risk. Large numbers in church.	• Fire extinguishers are checked according to regulations annually by the church. To be used by a competent person if needed and it is safe to do so.				
		• Users must keep the fire exits clear during any service or event and acquaint themselves with all fire exits.				





Activity: Any activity taking place in the church Location: All Saints Church Name of leader with responsibility: Rev Beverly Wats		Date of first risk assessn Time/frequency: tson Date to be reviewed: 7 th		4		
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
		 Follow set procedures – leader to raise the alarm with the congregation/group (via the PA system if in use) and to get other leaders to open doors and to clear the church and guide people down to the field (to avoid blown out glass.) Families to be reunited and checked by one of the above to see if anyone is missing. Celebrant/church wardens/group leader to phone emergency services using own mobile phone or from a nearby house. One of the above people to go to the entrance to meet the emergency services and one to check the church buildings are empty. Everyone to remain on the field until the fire is extinguished OR everyone 				





Location: All Saints	y taking place in the church Church h responsibility: Rev Beverly Wats	Date of first risk assessr Time/frequency: On Date to be reviewed: 7 ^t	-	24		
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
		accounted for and allowed to leave by fire marshall. Public should not re-enter the building unless fire marshalls, or fire service personnel give permission				
Specific areas of the	e building					
Entrance Hall:						
Steps by the door – front and back	Trip/fall	 Users to take care when exiting the building. 				
Door well mats	Trip/fall as mats wear and compact	 Users to report any wear in Faults and Repairs book. Mats to be replaced as required. 				
Internal doors into church	Fingers getting trapped	 Users to hook back door when people are using the church to give clear access if necessary. 				





Activity: Any activity taking place in the church Location: All Saints Church Name of leader with responsibility: Rev Beverly Wa		Time/frequency:					
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done	
Lobby by toilet: Gas meter	Gas leak	• Users to know where the gas main switch is to be able to turn it off in an emergency.					
Disabled Toilet: Cleaning products	Accessible - poison	 The Church will store these in cupboard secured with high bolt. Users to ensure doors bolted all the time so no access for children. medium 	•				
Loose brooms etc	Fall onto someone	Users to keep them clipped to the wall in the cupboard.					
Grit	Accessible to children	Church to keep in container.					
Hot water from tap	Burns/scalds	• Temperature is kept tolerable or sign put up if can't control heat.					
Water leaks	Flooding in the church	• Leaders to know where the water stop cock is to be able to turn it off in an emergency (remove wood from side wall by sink)	< .				
Flower cupboard: Stacked flower stands and steps	Risk of falling over	Users to keep the door locked and bolted. No children to have access to cupboard.					





Risk Assessment

Activity: Any activity taking place in the church Location: All Saints Church Name of leader with responsibility: Rev Beverly Wat		Date of first risk assessn Time/frequency: tson Date to be reviewed: 7 th	-	24		
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
Vases	Risk of breakage	Church to keep them under the sink/drainer area.				
Knife and scissors guillotine	Risk of cuts	Church to keep up out of reach of children				
Office: Kettle/lead Coffee Machine	Pulling hot water on yourself – scalds	 Users to make sure it is emptied after use and stored away from the edge of the worktop. Portable equipment owned by the church will be checked following HSE advice. To be used by responsible adults only. 				
Electrical equipment: computer, printer, photocopier, shredder, laminator, heater.	Electrocution	 Users to keep water away from electrical equipment Church to ensure equipment is Portable Appliance Tested (PAT) annually. 				
Staplers/Scissors	Cuts	Users to put out of reach/in drawer				
Main Church						





Location: All Saints C	v taking place in the church Church a responsibility: Rev Beverly Wats	Date of first risk assessn Time/frequency: on Date to be reviewed: 7 ^{ti}		24		
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
Door well mat	Trip/fall as mats wear and compact	 Users to report major wear and tear on Faults and Repairs booklet Replace when necessary. 				
Easter candle and Font	Falling over/burns	 Parents to supervise their children in the baptistery area. 				
Churchwarden's staffs and MU banner	Falling over	 Church to ensure clipped firmly. Parents to supervise their children. 				
Pictures on the wall	Falling/broken glass	 Church to ensure firmly fixed to wall. Users to clear up any breakages as soon as possible. 				
Large cross above altar	Falling on people below	 Church to check regularly that it is firmly fixed. 				
Moving the piano	Muscular damage/injury	• Do not move the piano , it is to remain on the piece of carpet that currently holds it in place.				





Activity: Any activity taking place in the church Location: All Saints Church Name of leader with responsibility: Rev Beverly Watso		Date of first risk assess Time/frequency: tson Date to be reviewed: 7		24		
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
Electrical wire to the organ by the choir corner	Trip and electrocution	Church to keep wires in casing				
Lamp by organ	Falling/trip on wires	Church to keep lamp by the wall so no trailing wires.				
Electrical fire hazard from organ	Fire risk	Church to keep maintained and serviced regularly.				
Drums and carpet	Trip hazard	Users to store in corner when not in use				
Use of candles/votives	Burns/fire in church/clothing catching fire	No candles to be used without prior permission.				
Floor grills for heating	Trip hazard/fire risk	Users to report in Faults and Repairs book if uneven or damaged.				





Risk Assessment

Location: All Saints (/ taking place in the church Church 1 responsibility: Rev Beverly Wa	Date of first risk assessn Time/frequency: tson Date to be reviewed: 7 th		4		
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
High level light bulbs – risk of falling from height whilst changing	Injury from falling off ladder	 Users to report any broken lights/lightbulbs in Faults and Repairs booklet When replaced, church to ensure use of long reach pole or if ladder used ensure second person is available to hold ladder. 				
Chairs and chair storage	Risk of chairs falling causing damage and/or injury	 Books must be removed from the book tray on back of chair before chairs are stacked Only store a maximum of 8 chairs without arms on a trolley. Only store a maximum of 5 chairs with arms, free-standing on the floor (not on the trolleys). Take care when moving trolleys and store safely in chair store When moving chairs take particular care to de-link them from other chairs and pick up 				





Activity: Any activity taking place in the church Location: All Saints Church Name of leader with responsibility: Rev Beverly Wat		Date of first risk assessment: 7 th January 2024 Time/frequency: Son Date to be reviewed: 7 th January 2024				
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
	Risk of damage to the floor	 no more than two chairs at a time Move the trolleys to the chairs rather than lots of individuals carrying chairs from one side of the church to the other, creating a hazard and a bottle-neck Take care when moving chairs that you do not scuff the floor, but pick up and put down carefully, do not drag across the floor. Spillages should be mopped up immediately and the floor wiped dry, do not leave the floor wet. 				
Children's Church	Activity packs to be provided for children attending services. Risk of infection to other children,	• All packs to be individually named and will be quarantined between services. Only to be used by the named child.				
Resource Library –	This area has signs of subsidence	and access to it has been closed for the time I	being.			
There is subsidence in this area.	Risk of damage from falling bricks or roofing.	The area is to be cordoned off with no access from the main body of the church				





Activity: Any activity taking place in the church Location: All Saints Church Name of leader with responsibility: Rev Beverly Wats		Date of first risk assessment: 7 th January 2024 Time/frequency: Itson Date to be reviewed: 7 th January 2024				
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
The Chapel of the Ho	bly Family – This area has signs of	subsidence and access to it has been close	d for the time being.	•		1
There is subsidence in this area.	Risk of damage from falling bricks or roofing.	• The area is to be cordoned off with no access from the main body of the church				
Chair Store Heavy items on shelves	Risk of damage from falling items	 Users to take care when moving things off shelves 				
Reading Room 2nd cupboard – (choir)	Falling papers/shelves	Church to maintain so that shelves do not fall out.				
3rd cupboard – boiler	Explosion/gas	 Church to ensure good ventilation maintained. Annual Maintenance. No unauthorized access to the boiler cupboard. 				
Stacking chairs	Falling	Users to ensure not more than 5 high.				
Gas heater	Burns/explosion	Users to keep guard in front and ensure nothing is put on top of it. Turn heater				





Activity: Any activity taking place in the church Location: All Saints Church Name of leader with responsibility: Rev Beverly Wa		Date of first risk assessment: 7 th January 2024 Time/frequency: Date to be reviewed: 7 th January 2024				
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
		down when no longer in use.Maintenance via annual service				
Choir robe store	Snapping rail – falling rail/robes	Users to take care when removing/placing items on the rail.	I			
Storage on floor cushions on top of choir robes.	Falling	Store carefully after use.				
Kitchenette	Scalds/electrocution	Ensure door is kept closed and children do not enter. To be used by responsible adults.	0			
Vestry Hanging rails	Rail breaking, robes falling.	Church to ensure not overloaded.				
Valuable items	Theft	Church to ensure safe remains locked and cupboards closed.	Ł			
Kettle	Flex being pulled – scald	Church to keep children out of Vestry except for the Crucifer.				



Activity Any activity taking place in the church



Parish of All Saints Church

Risk Assessment

Location: All Saints C Name of leader with	hurch responsibility: Rev Beverly Wat	Time/frequency: Date to be reviewed: 7 th January 2024				
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
		• Care to be taken when reaching for kettle.				
Cleaning products	Inhalation/swallowing hazardous chemicals	Church to ensure they are kept in cupboard in secure room.				
Communion wine	Underage drinking	Church to keep in secure room.				
Gas heater	Burns/Explosion	 Church to ensure it is not covered and properly ventilated. Church to arrange for annual servicing to take place. 				
Audio Visual Equipment Sound Equipment Portable projector Portable microphones	Electrocution/Trip Hazard	 Users to use as instructed and store on shelf out of reach. All leads protected with cable covers. PAT according to HSE guidance. All equipment will carry PAT label. 				
Fuse box	Electrocution	No unauthorized access, in secure room.				

Data of first rick according to 7th January 2024



Activity: Any activity taking place in the church



Parish of All Saints Church

Risk Assessment

Name of leader wi What are the hazards?	th responsibility: Rev Beverly Wa Who might be harmed and how?	Utson Date to be reviewed: 7 th What are you already doing?	January 2024 Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
High storage cupboards	Fall/damage to head	Church to use proper steps to not overreach and when open to secure properly. Store items carefully.				
Risks to Fabric Security	Theft	 Users to ensure that all windows and doors are locked shut before leaving the building. Users to lock the main exits if asked to do so. No extra keys to be cut by hirers. An upto-date list of key holders is kept by the churchwardens. 				
Failure to protect children and vulnerable adults Risk of abuse/harm	Physical/mental/sexual abuse	Church volunteers to ensure safeguarding policy is read and adhered to. At least 2 adults to be present in any room for any activity involving children and/or vulnerable adults. Adult/ child ratios to be maintained				

Date of first risk assessment: 7th January 2024





Activity: Any activity taking place in the church Location: All Saints Church Name of leader with responsibility: Rev Beverly Wats		Date of first risk assessment: 7 th January 2024 Time/frequency: Date to be reviewed: 7 th January 2024				
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done
		Users to ensure they have appropriate safeguarding measures (eg Guides to follow Girl Guiding UK safeguarding.)				
Fraud: Monetary cash on site	Risk of theft or fraud	 Users ensure cash is stored in the safe and kept locked and vestry door locked Sides people follow church procedures for managing Sunday collections Cashier and one other adult to follow church procedures for counting and banking cash. 				
Use of contractors: Unsafe contractors – ie not competent or properly resourced to conduct work safely	Harm to Users and premises	 Church to obtain written references/confirmation of abilities of contractors. Church to verify they are appropriately insured ie public and employer's liability. 				





Risk Assessment

Activity: Any activity taking place in the church Location: All Saints Church Name of leader with responsibility: Rev Beverly Watson		Time/frequency:	Date of first risk assessment: 7 th January 2024 Time/frequency: Date to be reviewed: 7 th January 2024				
What are the hazards?	Who might be harmed and how?	What are you already doing?	Do you need to do anything else to manage this risk?	Action by whom?	Action by when?	Done	
		 Church to confirm any work with our insurance company. Contractor to provide risk assessment before work commenced. 					

Risk assessment approved by: Beverly Watson, Incumbent

Benely watsa

Date of approval: 7th January 2024

Caroly M. Nice 113.

Risk assessment approved by: Carolyn Nicholls Church Warden

Date of approval: 7th January 2024